

As the Cause Map Demonstrates there were many causes that contributed to the collapse of the bridge. Wind was one of the more obvious causes. On the day the bridge failed, the wind was blowing across the roadbed at 42 Dm, the strongest wind the bridge had experienced. Another cause was the design of the bridge. The Tacoma Narrows Bridge was particularly narrow relative to its length, making the roadbed more flexible than other suspension bridges. Additionally, the bridge had shallow girders and was relatively weak in torsion compared to other suspension bridges built around the same time. The overall design of the bridge resulted in a structure that was weak in torsion and moved relatively easily in the wind.

Cause Map



In addition to the mechanical causes that contributed to the failure, there were a number of issues with the design process. One of the primary drivers behind the bridge design was cost reduction. The first design propsed for the Tacoma Narrows Firdge was a conventional suspension bridge that was estimated to cost \$111 million. The price of the bridge design that was actually built was of \$3 millions dollars cheaper. Additionally, the approved design was considered to be much more elegant and aesthetically pleasing. As in the case of all designs that failure, the design review process was also ineffective or the design flaws that contributed to the bridge collapse would have been identified prior to construction.