Reactor Vessel Head Degradation Davis-Besse Nuclear Power Station March 7, 2002

Even more detail can be added to this Cause

investigation the level of detail in the analysis

Custome

Service Go

Impacted

is based on the impact of the incident on the

organization's overall goals.

Map as the analysis continues. As with any

On March 7, 2002, during refueling, a cavity measuring approximately 4 x 6 inches was discovered that had completely eaten through the more than 6" thick reactor pressure vessel head of Unit #1 reactor at Davis-Besse Nuclear Power Station. Fortunately, the thin stainless steel cladding layer had held the reactor pressure, although it was not designed to do so. The loss of the vessel head was also a loss of a principal fission product barrier (one of the three responsible for ensuring radiaoctive fission products remain within the pressure boundary). This was an impact to the safety goal. The loss of a principal fission product barrier is also considered a "significant precursor to core damage" by the NRC, which is another impact to the safety goals. All told, the cavity resulted in nearly \$300 million worth in repairs and upgrades, and a two-year closure of the plant, during electricity production at Davis-Besse was severely reduced. These were impacts to the material, production, and customer service goals. Let's examine some of the causes of the cavity. A thorough root cause analysis built as a Cause Map can capture all of the cause in a simple, intuitive format that fits on one page.

Significant

precursor to

core damage

Safety Goal

Impacted

Material Goa

Plant closed for

2 years

Loss of

barrier

Damage to ressel - \$293 M repairs and upgrades

incipal fissior product

Safety Goal

Impacted


Goal

mpacted

Reduced

production of

electricity



AND

Inadequate

The cavity was caused by continued boric acid corrosion. The corrosion occurred when leaking coolant evaporated into boric acid. This occurred because of a through-wall crack in a nozzle caused by primary water stress corrosion cracking that was undetected. The corrosion also occured because the leakage was undetected, due to delayed inspections and an ineffective leakage detection methods.

Cavity through

entire reactor

pressure vesse

head

The boric acid was not removed because it was not viewed as a safety concern.

Cause Map Detail Level

